

Cultured Marble and Stone

Care & Cleaning Tips: Severe Temperature Changes

Cultured marble, granite & engineered stone share the contraction and expansion characteristics of natural marble. Attention to temperature change is particularly important during winter months when the temperature difference of the hot water in your heater and the temperature of the cold water lines is the greatest. Avoid running hot water exclusively in your sink. Rapid changes in water temperature can cause the bowl in your countertop to crack. Your top should last a lifetime if the proper care is taken.

Never run straight hot water exceeding 150° F into the basin as this can cause hair-line cracks. For added safety, keep hot water thermostat at 150° F or below.

Your North Coast Cultured Products countertop is a quality benchmark in the industry. With a minimal amount of care, you will have many happy years to enjoy its beauty. You can be proud your cultured marble counter top is manufactured in the USA by North Coast Cultured Products.

Source: http://northcoastmarble.com/tips_tempchanges.php