Tweed Laboratory Centre



Page 1 of 2

191851

PO8645

13/06/2019

Tweed Laboratory Centre, 46 Enterprise Avenue, Tweed Heads South NSW 2486 Australia Phone: 07 5569 3103 Fax: 07 5524 2676 Email: samplereception@tweed.nsw.gov.au ABN: 90 178 732 496 (All correspondence: Tweed Shire Council PO Box 816 Murwillumbah NSW 2484) www.tweed.nsw.gov.au/tweedlab/

FINAL CERTIFICATE OF ANALYSIS

Client: **Broken Head Quarry**

Address: PO Box 165

> **BYRON BAY** NSW 2481

Attention:

Copy To:

Leonie Rowe

Client Reference: Date of Report:

Lims1 Report No:

All pages of this report have been checked and approved. This document may not be reproduced except in full.

Taken By: Client No of Samples:

Date Taken: 05/06/2019 **Date Testing Commenced:** 05/06/2019 **Date Received:** 05/06/2019 **Date Testing Completed:** 13/06/2019

CHEMICAL Quarry - Air Monitoring PO8645 **REPORT** Job Description:

LIMS No.	Sample/Site Identification	Sample/Site Description		
191851-1	SPD1	1		
191851-2	SPD2	2		
191851-3	SPD3	3		
191851-4	SPD4	4		

Dr Paul J Wright (Laboratory Coordinator) paulw@tweed.nsw.gov.au

Page 2 of 2



Tweed Laboratory Centre

Client: Broken Head Quarry

 Address:
 PO Box 165
 Lims1 Report No:
 191851

 Date Testing Completed:
 13/06/2019

Date of Report: 13/06/2019

BYRON BAY

NSW 2481

Attention: Leonie Rowe

CHEMICAL REPORT Job Description: Quarry - Air Monitoring PO8645

REPORT COMMENTS

Additional information relevant to this report can be found in the Sample Receipt Notice and Chain of Custody. Measurement Uncertainty available upon request.

Key: LOR = Limit of reporting

A = NATA accreditation does not cover the performance of

this service

* = Value is considered an estimate

NP = Not present
< = Less than
> = Greater than

ANALYSIS RESULTS

Sample Identification:			SPD1	SPD2	SPD3	SPD4
Date Taken:			05/06/2019	05/06/2019	05/06/2019	05/06/2019
Test	Method	Units	191851-1	191851-2	191851-3	191851-4
^Air Monitoring	P13	g/m2/mth	0.4	1.9	2.0	1.7
^Ash Content	P13	g/m2/mth	0.1	1.2	0.3	1