Tweed Laboratory Centre



Page 1 of 2

Tweed Laboratory Centre, 46 Enterprise Avenue, Tweed Heads South NSW 2486 Australia
Phone: 07 5569 3103 Fax: 07 5524 2676 Email: samplereception@tweed.nsw.gov.au ABN: 90 178 732 496
(All correspondence: Tweed Shire Council PO Box 816 Murwillumbah NSW 2484)

www.tweed.nsw.gov.au/tweedlab/

FINAL CERTIFICATE OF ANALYSIS

Client: Broken Head Quarry

Address: PO Box 165

BYRON BAY NSW 2481

Attention: Leonie Rowe

Copy To:

Lims1 Report No: 190791
Client Reference: PO 08643

Date of Report: 19/03/2019

All pages of this report have been checked and approved. This document may not be reproduced except in full.

Taken By: Laboratory Staff No of Samples:

 Date Taken:
 06/03/2019
 Date Testing Commenced:
 06/03/2019

 Date Received:
 06/03/2019
 Date Testing Completed:
 15/03/2019

CHEMICAL REPORT Job Description: Quarry - Air Monitoring PO: 08643

LIMS No.	Sample/Site Identification	Sample/Site Description		
190791-1	SPD1	1		
190791-2	SPD2	2		
190791-3	SPD3	3		
190791-4	SPD4	4		

Dr Paul J Wright (Laboratory Coordinator) paulw@tweed.nsw.gov.au

Page 2 of 2



Tweed Laboratory Centre

Client: Broken Head Quarry

 Address:
 PO Box 165
 Lims1 Report No:
 190791

 Date Testing Completed:
 15/03/2019

Date of Report: 19/03/2019

BYRON BAY

NSW 2481

Attention: Leonie Rowe

CHEMICAL REPORT Job Description: Quarry - Air Monitoring PO: 08643

REPORT COMMENTS

Additional information relevant to this report can be found in the Sample Receipt Notice and Chain of Custody. Measurement Uncertainty available upon request.

Key: LOR = Limit of reporting

^ = NATA accreditation does not cover the performance of

this service

* = Value is considered an estimate

NP = Not present
< = Less than
> = Greater than

ANALYSIS RESULTS

Sample Identification:			SPD1	SPD2	SPD3	SPD4
Date Taken:			06/03/2019	06/03/2019	06/03/2019	06/03/2019
Test	Method	Units	190791-1	190791-2	190791-3	190791-4
^Air Monitoring	P13	g/m2/mth	1.8	3.6	15.5	4.7
^Ash Content	P13	g/m2/mth	1.8	3.5	14.7	4.7