# **Tweed Laboratory Centre**



Page 1 of 2

Tweed Laboratory Centre, 46 Enterprise Avenue, Tweed Heads South NSW 2486 Australia
Phone: 07 5569 3103 Fax: 07 5524 2676 Email: samplereception@tweed.nsw.gov.au ABN: 90 178 732 496
(All correspondence: Tweed Shire Council PO Box 816 Murwillumbah NSW 2484)

www.tweed.nsw.gov.au/tweedlab/

#### FINAL CERTIFICATE OF ANALYSIS

Client: Broken Head Quarry

Address: PO Box 165

BYRON BAY
NSW 2481

Lims1 Report No: 193688
Attention: Leonie Rowe Client Reference: PO:

Attention. Leonie Rowe Cheft Reference.

JWNOV2019

Copy To: Date of Report: 19/11/2019

All pages of this report have been checked and approved. This document may not be reproduced except in full.

Taken By: Client No of Samples: 4

 Date Taken:
 06/11/2019
 Date Testing Commenced:
 06/11/2019

 Date Received:
 06/11/2019
 Date Testing Completed:
 19/11/2019

CHEMICAL REPORT Job Description: Quarry - Air Monitoring PO:JWNOV2019

 LIMS No.
 Sample/Site Identification
 Sample/Site Description

 193688-1
 SPD1
 1

 193688-2
 SPD2
 2

 193688-3
 SPD3
 3

 193688-4
 SPD4
 4



Page 2 of 2

193688



# **Tweed Laboratory Centre**

Client: **Broken Head Quarry** 

Lims1 Report No: Address: PO Box 165 **Date Testing Completed:** 19/11/2019 Date of Report: 19/11/2019

**BYRON BAY** 

NSW 2481

Attention: Leonie Rowe

**CHEMICAL REPORT Job Description:** Quarry - Air Monitoring PO:JWNOV2019

### **REPORT COMMENTS**

Additional information relevant to this report can be found in the Sample Receipt Notice and Chain of Custody. Measurement Uncertainty available upon request.

Key: LOR = Limit of reporting

= NATA accreditation does not cover the performance of

= Value is considered an estimate

NP = Not present = Less than = Greater than

#### **ANALYSIS RESULTS**

Sample Identification:			SPD1	SPD2	SPD3	SPD4
Date Taken:			06/11/2019	06/11/2019	06/11/2019	06/11/2019
Test	Method	Units	193688-1	193688-2	193688-3	193688-4
^Air Monitoring	P13	g/m2/mth	3.6	1.8	0.7	1.6
^Ash Content	P13	g/m2/mth	3.2	0.6	0.7	1.6